

# WIRING DIAGRAM - 4 GANG - FOR DOOR PLACEMENT

## MASTER SWITCH

12 VOLT — RED  
HOT FEED  
TO FUSE BOX

BLACK — GROUND

BROWN — TO DRIVER'S  
SIDE MOTOR

